Revised 12/03

CORRES CONTROL INCOMING LTR NO

00149 RF04

DUE DATE

ACTION

## RECEIVED

2634 ht 3 25 P 3 12 Department of Energy

CON TREMIET DEROCKY FLAIS PROJECT OFFICE 10808 HIGHWAY 93 UNIT A GOLDEN COLORADO 80403 8200

MAR 2 2 2004

04-DOE-00181

DIST		ENC
BERARDINI JH	X	IX.
BOGNAR ES	X	X
BROOKS L	IX	X
BUTLER L	IX	X
CARPENTER M	X	X
CROCKETT G A.	1	
DECK, C A	TX	X
DEGENHART K R	X	X
DIETER T J		
DIETERLE S E		
FERRERA D W	X	X
GIACOMINI J J		_
LINDSAY D C	X	$\mathcal{X}^{-}$
LONG J W		
LYLE J L		
MARTINEZ L A	X	X
NAGEL R E	X	X
NESTA S	X	V
NORTH K	X	Ŷ
PARKER A M	X	X
RODGERS A D		
SHELTON D C	X	X
SPEARS M S		
PIZZISTO. V.		
TUOR N R	X	X
WIEMELT K	X	Ż
WILLIAMS J L		
ZAHM C	X	X
Freiboth C	X	$\overline{\chi}$
,		

Mr Steven II Gunderson Rocky Flats Cleanup Agreement Project Coordinator Colorado Department of Public Health and Environment 4300 Cherry Creek Drive South Denver, Colorado 80246-1530

Dear Mr Gunderson

Please find enclosed the Rocky Flats Cleanup Agreement Type I Building Disposition

Closeout Report for Building 549 Fitness Facility Questions may be directed to Gary

Morgan, at (303) 966-6003

Sincerely,

Joseph A Legare, Director Project Management

Enclosure

cc w/o Fncl

F Lockhart OOM, RIPO

S Nesta, K-H, RISS Fnv

C Freiboth K-H, RISS D&D

K Wiemeli, K-H RISS D&D

N Adler, USEPA

cc w/Encl

G Morgan, CP, RFPO

Administrative Record

Reviewed for Addressee Corres Control RFP

COR CONTROL

PATS/130

ADMIN RECORD


Ref Ltr # OYRFOODS

DOE ORDER#

5400

ADMIN RECORD





February 23,2004

04-RF-00235

Gary P Morgan, Functional Lead Cadre Project Management Division DOE, RFPO

TRANSMITTAL OF CLOSE-OUT REPORT FOR B549 -- FEG-009-04

Attached is the Closeout **Report** for the Type 1 facility **B549** Fitness Facility Please note that a copy of this report **has been** submitted to the CERCLA AR by the Kaiser-Hill **RISS** project

Please contact Steve Nesta x6386 with questions or concerns

Frank E Gibbs

Deputy Project Manager

Remediation, Industrial D&D, and Site Services

Attachment

As Stated

SMN pvt

Orig and I cc - Gary P Morgan

cc

Joe Legare

5400

Section A Facility Data			
Facility No B549			
Facility Descriptor Fitness Facil	lity		
Project RISS			
Date of Demolition 11/19/03			
Additional Information Attached			
(Must include information on invironmental i	releases and conditions & site at turnover to Environmental Restoration)		
Section B Final Characterization D			
Reconnaissance Level Characterization	Report 10/09/03		
(concurrence received)	NIIA		
In-process Characterization	NIA PROCESSION AND A PR		
Pre-Demolition Survey Report (approva			
Post-Demolition Survey Report (as nece	ssan) NIA		
Section C Waste Data (complete car Sanitary Disposal	tegories as appropriate)		
Disposal Site	sposal Site BFI Landfill, Golden CO		
Waste Volume (m³)	200		
Waste Weight (tons)	141		
Additional Information	Waste included building structure, pad and surrounding asphalt		
Hazardous Disposal			
Disposal Site	Kettleman Hills Facility, Kettleman City, CA or Bethlehem Apparatus		
•	Co, Hellertown, PA		
Waste Volume (m³)	Less than 1 m <sup>3</sup>		
Additional Information	Circuit boards, fluorescent lamps, Hg switches, etc. were moved to a		
	RFCA Temporary Unit and combined with like waste streams for		
	disposal		
TSCA Waste Disposal (other than			
ACM)			
Disposal Site	BFI Landfill, Golden CO		
Waste Volume (m³)	< 1m <sup>3</sup>		
Additional Information	PCB ballasts were sent to the landfill as PCB Bulk Product Waste comingled with building debiis		
Asbestos Waste Disposal			
Disposal Site			
Waste Volume (m³)			
Additional Information	No asbestos waste was generated		
Low-Level Waste Disposal	NIA		
Additional Information	No LLW was generated		
Low-Level Mixed Waste Disposal Additional Information	N/A No LLMW was generated		
	140 PENT II WAS Relictated		
Recycled Material	1		
Additional Information			
Property Disposition			
Receiver Locations (major items only)	NIA		
Additional Information	Miscellaneous small items suitable for resale were removed by PU&D		
Section D. Americals			
Section D Approvals Kaiser-Hill Project Manager	America - CJ FARTAUTA 02/20104		
Nama/81	Ammum - CJ FARTAUM CZ WOL		
Namer			
$\mathcal{V}$	,		

## Additional Facility Information

Building 549 was a 1920 sq. ft. metal frame building constructed on a concrete slab. The walls and coiling were insulated metal sheets attached to a steel frame with sprayed-on insulation. Building 549 was last used as a Fitness Center, and was constructed in 1957 with the following utilities, gas (propane supplied by tank) water, sanitary, and electric. Fire protection was provided by wall-mounted fire extinguishers.

Originally, Building 549 was an electrical support building operated by J. A. Jones. From 1994 to 2001 the building was used to house and support Southside Radion personnel. As a Radion support facility, the building was used to count smears, store air samples, and store Radion materials. During this time, the building had a RMA in the northwest portion of the building, which was used to store radiological sources. None of these sources where known to have leaked. In 2001 the facility was closed and left vacant for about 6 months before being converted to a fitness center. The building has no history of building contamination.

The entire facility, structure, and slab were removed during D&D activities. The electric service was above ground and completely removed. Ferrell Gas removed the propane tank prior to demolition, and the delivery lines were left in the building during demolition. Water and sewer lines were removed to a depth of four feet. Water and sewer lines at or below four feet have been left in place. The sewer lines were flushed, cut (disconnected), and grouted. The lines remaining (below four feet) are not active. See attached map for disconnect locations.

Building 549 was associated with or located near the following active IHSSs, PACs, and UBCs,

- 1) PAC 300-186 "Valve Vault 12", Active
- 2) PAC 500-117 1' North Chemical Site Storage" Active
- 3) PAC 500-904 "Transformer Leak -223-11223-2", Active

The Environmental Restoration (ER) group is performing full characterization of the surrounding soils ER will complete and close site activities based on the outcome of their sampling efforts

U.S. Department of Energy Rocky Pats Environmental Technology Site Rocky Flats Environmental Technology Site Demolshed Buildings

Taved Roads

Lakes **Building 549** State Plane Coordinate Projector Colorede Castral Zone (3475) Daken NADZ7 nch equals 25 feet Dirt Roads CH2MHILL Buildings 1296 Streams Fences Trails -Appreximate location of san tary sewer Approximate location of water service disconnection

Standard Map Features

KAISEL·HUL

Acres 14 2003